



PASF _Tools Training plan:

Eq.No	Equipment Name	Training slot	Training schedule for every week
1.	Environmental Chamber ATT-PASF018	4 slot	Tuesday, Thursday
2.	Climate Chamber Votsch -1-PASF002	4 slot	Monday, Friday
3.	Pneumatic Pressure controller 20bar PASF011	4 slot	Tuesday, Thursday
4.	Pneumatic Pressure controller 200bar PASF017	4 slot	Monday, Friday
5.	Hydraulic Dead Weight Tester-PASF021	4 slot	Tuesday, Thursday
6.	Chemical Wet Bench	4 slot	Tuesday, Thursday
7.	Pressure cycling Tester PASF027	4 slot	Monday, Friday
8.	High power Plasma Cleaner-PASF015	5 slot	Tuesday, Thursday
9.	Fiber Laser Marking Tool-PASF009	5 slot	Monday, Friday
10.	REMI Centrifuge PASF016	4 slot	Tuesday, Thursday
11.	Semi-automatic wire bonder HB16-PASF005	10 slot (8 slot)	Tuesday, Thursday, Wednesday
12.	Flip chip Bonder PASF024	10 slot (8 slot)	Tuesday, Thursday, Wednesday
13.	Helium Leak Tester -PASF 008	4 slot	Monday, Friday
14.	3D Printer	4 slot	Tuesday, Thursday
15.	Soldering and Desoldering station PASF020	4 slot	Tuesday, Thursday
16.	Hot Air oven -PASF013	4 slot	Monday, Friday
17.	Vacuum oven PASF026	4 slot	Tuesday, Thursday
18.	Manual DC Probe Station-PASF007	4 slot	Tuesday, Thursday